SAFE[®] 2014 (v14.1.1) Release Notes

© Copyright Computers and Structures, Inc., 2015

Notice Date: 2015-07-14

This file lists all changes made to SAFE since the previous version. **Most changes do not affect most users.** Incidents marked with an asterisk (*) in the first column of the tables below are more significant and are included in the ReadMe file.

Changes from v14.1.0 (Released 2015-06-12)

Modeling

Enhancements Implemented

*	Incident	Description
	80418	An enhancement was made to add the Australian rebar property set to the Reinforcement Bar Sizes
		form.

Punching Shear Design Enhancements Implemented

*	Incident	Description
	65837	An enhancement has been made for slab punching shear calculations to allow for openings that are
		within or intersect the punching perimeter. Earlier these conditions would cause the punching shear
		calculations not to be performed and a N/C (not calculated) was reported.

Installation and License Enhancements Implemented

*	Incident	Description
	80321	All significant installed EXE and DLL files are now digitally signed to avoid sand-boxing and other
		interference from anti-virus products. It is important to note that there never was a threat from any
		of the installed files in any previous release, but a few anti-virus products are overly cautious, which
		could cause them to prevent the software from running. No results were affected.

Miscellaneous Enhancements Implemented

*	Incident	Description
	80680	The version number has been changed to v14.1.1 for a new minor release.

User Interface and Display Incidents Resolved

*	Incident	Description
	80952	An incident was resolved to enable the "Draw Dimensions Lines" tool button when the model is
		locked. The menu option for "Draw Dimension Lines" was available for locked models.

Analysis Incidents Resolved

*	Incident	Description
	80642	An incident was resolved where in some rare cases when running cracked slab analysis a program
		internal error message would pop up and the model could not be run. This was limited to v14.1.0.

Slab/Beam Design Incidents Resolved

*	Incident	Description
	79653	An incident was resolved for one-way shear design of slabs for the CSA A23.3-04 and CSA A23.3-
		14 codes where beta and theta values computed from section 11.3.6.4 were too conservative when
		the slab/mat thickness was less than or equal to 350mm. Section 11.3.6.2 is now enforced for
		slab/mats less than 350mm thick.
	80898	An incident was resolved where assigning the beam design overwrite for "Ignore PT when
		designing beam" was not working. It was working when assigned through the right button
		information dialog.

Punching Shear Design Incidents Resolved

*	Incident	Description
	80905	An incident was resolved where the program was unable to correctly trace the area edge for
		computing the punching shear when the area edge was curved.

Detailing

*	Incident	Description
	69900	An incident was resolved where detailing options using right click of the mouse were not available
	80516	in the Model Explorer.
	80546	

Results Display and Output Incidents Resolved

*	Incident	Description
	72292	An incident was resolved where the beam rebar information shown on mouse move was giving the
		rebar without imposing minimum requirements even if the option to impose minimum was on. This
		was limited to the mouse move information only. The design and the display were not affected.

Documentation

Incidents Resolved

*	Incident	Description
	34410	The reinforced concrete design and prestress design manuals have been updated for ACI 318-08 and ACI 318-11 design codes to clarify the enforcement of ACI 421 equations which are used in the program. No design results were affected.
	74776	The reinforced concrete design manual and prestress design manual have been updated to indicate that the reinforcing ratio in punching shear is reported as an average of the column design strip ratios for BS 8110-97, Eurocode 2-2004, Hong Kong 2004 and 2013 and Singapore CP 65-99 codes. No design results were affected.
	79953	The design manuals have been updated to reflect the removal of I23 for the corner columns from the punching shear calculation. This change was released in v14.1.0. No change in design results from v14.1.0.