SAFE Version 8.1.1
Release Notes

© Copyright Computers and Structures, Inc., 2007

Release Date: 2007-10-19

This file lists all changes made to the SAFE since the last release. **Most changes do not affect most users.** Significant issues are indicated with an exclamation mark (**!**) in the first column of the tables below.

Changes from V8.1.0 (2007-03-16) to V8.1.1 (2007-10-19)

User Interface and Display
Incidents Resolved

!	Incident	Description
	13172	EMF files captured by the *File > Capture Enhanced Metafile* command were not being correctly scaled for some machines, cutting off part of the picture. This has been corrected for capturing the current window. The option to capture a user region in the current window has been removed.

Design
Enhancements Implemented

!	Incident	Description
!	13037	Design check has been added for the ACI 318-05 design code.
!	13038	Design check has been added for the CAN/CSA A23.3-04 design code.
!	13242	The design manual has been updated to include the two new design codes.

Design
Incidents Resolved

!	Incident	Description
!	12660	The punching shear perimeter was being incorrectly calculated from default column sizes for points supported on springs. This has been resolved. The punching shear perimeter at load points and at points supported by restraints or columns was correct and has not been changed.

Miscellaneous
Incidents Resolved

!	Incident	Description
	13082	CSI phone numbers have been changed in the program and documentation. The new voice number is 1-510-649-2200. The new fax number is 1-510-649-2299.
	13087	Version number changed to 8.1.1