

ETABS v19.0.2 Release Notes

© 2020 Computers and Structures, Inc.

Notice Date: 21-December-2020

This document lists changes made to ETABS since v19.0.1, released 15-December-2020. Items marked with an asterisk (*) in the first column are more significant.

Documentation

Enhancements Implemented

*	Ticket	Description
	5646	The "ETABS User's Guide" manual has been updated to reflect the latest features and graphical user interface.

Installation and Licensing

Enhancements Implemented

*	Ticket	Description
	5797	The version number has been changed to 19.0.2 for a new minor release. This version is compatible with v19.0.1, so that analysis and design results run in one version can be accessed in the other version.

Application Programming Interface (API)

Incidents Resolved

*	Ticket	Description
	5481	An incident was resolved for the Application Programming Interface (API) where the function <code>cPointObj.GetConnectivity</code> was not working correctly. The error affected ETABS version 19.0.0 and 19.0.1.
	5804	An incident was resolved for the Application Programming Interface (API) which affected the function <code>cDesignCompositeBeam.StartDesign</code> . The function did not start composite beam design, even when called in models in which it should. This affected ETABS v19.0.1 only.

Data Files

Incidents Resolved

*	Ticket	Description
*	5801	An incident was resolved where an abnormal termination error could occur when closing ETABS on some machines. This was caused by one or more of the files in the user settings folder being set to read-only access. This could occur due to explicit action by the user, or in some cases by Windows update. This error did not affect model files or any results. This issue was partially corrected with ETABS v19.0.1, but further corrections were required. Note that maintaining read-only access will prevent these files from being updated as expected, but will no longer trigger the error message.